



Technical Fire Safety

Technical Bulletin No 21

Subject	Detectomat RCP 6B Wireless Fire Detection System
Date	12/05/2009
Originator	Neville Mullings
Review Date	12/05/2012

The Detectomat “RCP Wireless Fire Detection System” has been installed, in error, in some premises within our region where a BS5839 pt.1 or BS5839 pt.6 system has been specified.

Whilst the system may be suitable in some circumstances, and elements of the system comply with relevant parts of BS5839, the system as a whole does not meet the specific requirements of some aspects of BS5839 part 1 or BS5839 part 6 installations.

These systems should not be accepted where a fully compliant BS5839 system has been specified.

For further system information visit: www.detectomat.com